

	A	B	C	D	E	F
1	## North America Emission Control Area Fuel Oil Non-Availability Report					
2	## ECA0100					
3	## 1	2	3	4	5	6
4	##					
5	##(Include Double Pound for comments, not form fields)					
6	##Report Form ID	Ship Operator Name	Vessel Name	Flag Country	IMO ID Number	Date of ECA First Notice
7	ECA0100	SWISSMARINE SERVICES SA	KONSTANTINOS II	LIBERIA	9595278	11/14/2013

	G	H	I	J	K
1					
2					
3	7	8	9	10	11
4					
5					
6	Location of ECA First Notice	Name of Ports after First Notice	Name of Last Port before ECA Entry	Name of Port with Fuel Oil Supply Disruption	Name of Original Fuel Supplier with Disruption
7	Port Kelang	Bontang	Bontang	NA	NA

	L	M	N	O	P	Q
1						
2						
3	12	13	14	15	16	17
4						
5						
6	Number of Fuel Suppliers Contacted	Date of Entry in the ECA	Time of Entry in the ECA	Sulfur Content of Non-Compliant Fuel Oil	Projected Hours on Main Propulsion	Name of First POC
7	1	12/11/2013	1300	2.65	280	Barbers Point

	R	S	T	U	V
1					
2					
3	18	19	20	21	22
4					
5					
6	Compliance Fuel Oil Available at First POC?	Plan to Bunker Compliant Fuel Oil at First POC?	Number of fuel suppliers contacted at First POC	Name of Second POC	Compliant Fuel Oil at Second POC?
7	N	N	NA	NA	NA

	W	X	Y	Z
1				
2				
3	23	24	25	26
4				
5				
6	Plan to Bunker Compliance Fuel Oil at Second POC?	Number of Fuel Suppliers Contacted at the Second POC?	Date of Exit from ECA?	Time of Exit from ECA?
7	NA	NA	12/23/2013	0900 lt

	AA	AB	AC	AD	AE
1					
2					
3	27	28	29	30	31
4					
5					
6	Has this vessel operated in the ECA in previous 12 months?	Number of Separate Visits to the ECA	Number of Ports visited in the ECA	Previously submitted ECA0100 forms?	Number of Submitted Reports
7	N	NA	NA	Y	11

	AF	AG	AH
1			
2			
3	32	33	34
4			
5			
6	Designated Corporate Official Name	Designated Corporate Official E-mail	Designated Corporate Official Phone Number
7	Mr Joshua Hawkins	Operations@swissmarine.ch	+41 228271895

	AI	
1		
2		
3		35
4		
5		
6	Description of Actions to Achieve Compliance	
7	Vessel was delivered DLOSP Port Kelang, where no LSFO was available. The vessel was then instructed to sail to Bontang to load coal, where also no LSFO is available. Also at discharge port Barbers Point no LSFO available.	